

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start		Rating **	M	Issue No.	3
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0556_01_f_2014_3				
Action/Comments					
Inspector Comments: The members in the district have not been flood fight trained recently according to the district manager.					

No Photos

LM Start		Rating **	M	Issue No.	6
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0556_01_s_2012_6				
Action/Comments					
Inspector Comments: District president has the O&M Manual.					

No Photos

LM Start		Rating **	M	Issue No.	8
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0556_01_f_2014_8				
Action/Comments					
Inspector Comments: According to the district manager, when they need supplies they will order them, there are no supplies stored.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	0.08	Rating **	U	Issue No.	72
LM End	0.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.237925 °	38.236055 °
				-121.518200 °	-121.518040 °
DWR ID	DWR_RD0556_01_s_2015_72				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the unacceptable wild growth.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_72\_20150430\_00023.jpg




RD 556 Unit 1 looking back upstream wild roses and other tall weeds on the levee slope.

LM Start	0.16	Rating **	M	Issue No.	381
LM End	0.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.236797 °	38.232032 °
				-121.518073 °	-121.522000 °
DWR ID	DWR_RD0556_01_s_2015_381				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	0.22	Rating **	U	Issue No.	26
LM End	1.70	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.236055 °	38.224305 °
				-121.518035 °	-121.537263 °
DWR ID	DWR_RD0556_01_f_2014_26				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: The woody tree growth blocks view of the levee slope.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_26\_20150430\_00025.jpg



Woody tree growth on the landward levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	0.27	Rating **	U	Issue No.	30
LM End	0.61	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.235427 °	38.231538 °
				-121.518523 °	-121.522553 °
DWR ID	DWR_RD0556_01_f_2014_30				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: Remove the young willow trees from waterside slope.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_30\_20150312\_00009.jpg



Unacceptable wild tree growth on the waterside slope.

LM Start	0.42	Rating **	U	Issue No.	61
LM End	0.42	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.233775 °	38.233775 °
				-121.520351 °	-121.520351 °
DWR ID	DWR_RD0556_01_f_2012_61				
Action/Comments					
Tree or limb					
Inspector Comments: There is a dead tree at this location. Remove it from the levee section. The district is aware of this issue.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_61\_20150430\_00027.jpg



This fallen tree hasn't been removed from levee section waterward.

LM Start	0.47	Rating **	M	Issue No.	32
LM End	0.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.233138 °	38.232032 °
				-121.520958 °	-121.522003 °
DWR ID	DWR_RD0556_01_f_2014_32				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**


## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	0.62	Rating **	U	Issue No.	376
LM End	0.90	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.231535 °	38.228602 °
				-121.522675 °	-121.526289 °
DWR ID	DWR_RD0556_01_s_2014_376				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: District should remove these unacceptable fig trees from the landside levee section.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_376\_20150430\_00028.jpg



Remove the fig trees on the landside shoulder and toe.

LM Start	0.66	Rating **	M	Issue No.	7
LM End	1.34	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.231011 °	38.227508 °
				-121.523246 °	-121.532396 °
DWR ID	DWR_RD0556_01_s_2013_7				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	0.80	Rating **	M	Issue No.	12
LM End	3.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.229459 °	38.208959 °
				-121.524805 °	-121.541368 °
DWR ID	DWR_RD0556_01_s_2012_12				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	0.95	Rating **	M	Issue No.	1
LM End	1.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.228016 °	38.227854 °
				-121.526868 °	-121.530291 °
DWR ID	DWR_RD0556_01_f_2014_1				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	1.05	Rating **	M	Issue No.	36
LM End	1.27	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.226780 °	38.227966 °
				-121.527465 °	-121.531176 °
DWR ID	DWR_RD0556_01_f_2012_36				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	1.08	Rating **	M	Issue No.	14
LM End	1.08	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.226887 °	38.226887 °
				-121.528022 °	-121.528022 °
DWR ID	DWR_RD0556_01_s_2012_14				
Action/Comments					
Note and monitor erosion site.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	1.31	Rating **	M	Issue No.	45
LM End	1.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.227788 °	38.227788 °
				-121.531825 °	-121.531825 °
DWR ID	DWR_RD0556_01_f_2014_45				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	1.34	Rating **	M	Issue No.	384
LM End	1.34	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.227576 °	38.227561 °
				-121.532293 °	-121.532306 °
DWR ID	DWR_RD0556_01_f_2013_384				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	1.37	Rating **	M	Issue No.	29	
LM End	1.38	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start	End	
Item	Trim / Thin Trees			38.227320 °	38.227216 °	
				-121.532707 °	-121.532870 °	
DWR ID	DWR_RD0556_01_s_2013_29					
Action/Comments						
Thin trees to allow visibility of the ground and room to flood fight.						

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	1.39	Rating **	M	Issue No.	79
LM End	1.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.227082 °	38.227072 °
				-121.533010 °	-121.533083 °
DWR ID	DWR_RD0556_01_s _ 2015_79				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	1.40	Rating **	M	Issue No.	21
LM End	1.40	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.227016 °	38.227016 °
				-121.533105 °	-121.533105 °
DWR ID	DWR_RD0556_01_f _ 2012_21				
Action/Comments					
Note and monitor erosion site.					

No Photos

LM Start	1.43	Rating **	M	Issue No.	40
LM End	1.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.226537 °	38.226537 °
				-121.533512 °	-121.533512 °
DWR ID	DWR_RD0556_01_f _ 2012_40				
Action/Comments					
Note and monitor erosion site.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	1.50	Rating **	M	Issue No.	22
LM End	1.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.225840 °	38.225840 °
				-121.534157 °	-121.534157 °
DWR ID	DWR_RD0556_01_s _ 2012_22				
Action/Comments					
Note and monitor erosion site.					
Inspector Comments: Monitor this erosion.					

No Photos

LM Start	1.57	Rating **	M	Issue No.	386
LM End	1.67	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.224995 °	38.224486 °
				-121.535094 °	-121.536766 °
DWR ID	DWR_RD0556_01_f _ 2013_386				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	1.75	Rating **	U	Issue No.	49
LM End	1.99	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.224120 °	38.223590 °
				-121.538137 °	-121.542387 °
DWR ID	DWR_RD0556_01_f _ 2014_49				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: Remove the unacceptable tree growth from the levee section on the waterward side.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_49\_20150312\_00011.jpg



Woody tree growth blocks view of the waterward slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	1.92	Rating **	M	Issue No.	387
LM End	4.12	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.223713 °	38.200105 °
				-121.541216 °	-121.545338 °
DWR ID	DWR_RD0556_01_f_2013_387				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	2.17	Rating **	M	Issue No.	50
LM End	3.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.221937 °	38.210658 °
				-121.544638 °	-121.539230 °
DWR ID	DWR_RD0556_01_f_2014_50				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	2.47	Rating **	M	Issue No.	42
LM End	2.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.217757 °	38.217285 °
				-121.543827 °	-121.543693 °
DWR ID	DWR_RD0556_01_f_2012_42				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	2.72	Rating **	M	Issue No.	88
LM End	2.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.215125 °	38.215085 °
				-121.540757 °	-121.540655 °
DWR ID	DWR_RD0556_01_s _ 2015_88				
Action/Comments					
Schedule repair of erosion site prior to the next inspection.					
Inspector Comments: Trees fell causing this erosion. The ground is sandy at this location.					

No Photos

LM Start	3.13	Rating **	M	Issue No.	62
LM End	3.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.211060 °	38.210913 °
				-121.538132 °	-121.538462 °
DWR ID	DWR_RD0556_01_f _ 2014_62				
Action/Comments					
Repair the levee slope damaged by livestock and prevent large animal access.					
Inspector Comments: Possible beaver den in area; activity at this location.					

No Photos

LM Start	3.13	Rating **	U	Issue No.	90
LM End	3.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.211040 °	38.210373 °
				-121.538123 °	-121.539982 °
DWR ID	DWR_RD0556_01_s _ 2015_90				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Remove wild growth, trim under the fig trees, and spray the wild berries.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	3.17	Rating **	M	Issue No.	52
LM End	3.18	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.210839 °	38.210767 °
				-121.538773 °	-121.538952 °
DWR ID	DWR_RD0556_01_f_2012_52				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	3.17	Rating **	M	Issue No.	91
LM End	3.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.210787 °	38.210518 °
				-121.538877 °	-121.539725 °
DWR ID	DWR_RD0556_01_s_2015_91				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	3.24	Rating **	M	Issue No.	65
LM End	3.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.210363 °	38.210270 °
				-121.540020 °	-121.540207 °
DWR ID	DWR_RD0556_01_s_2013_65				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	3.26	Rating **	M	Issue No.	395
LM End	3.37	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.210185 °	38.208899 °
				-121.540264 °	-121.541340 °
DWR ID	DWR_RD0556_01_f_2013_395				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: This wild growth is unacceptable and blocking visibility and access.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_395\_20150312\_00022.jpg



Unacceptable wild growth of cactus completely blocking visibility of the entire levee section.

LM Start	3.26	Rating **	M	Issue No.	13
LM End	3.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.210145 °	38.210145 °
				-121.540337 °	-121.540337 °
DWR ID	DWR_RD0556_01_f_2012_13				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: These trees need to be trimmed and thinned in order to see the ground.					

No Photos

LM Start	3.59	Rating **	U	Issue No.	68
LM End	3.85	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.205630 °	38.202080 °
				-121.541647 °	-121.541003 °
DWR ID	DWR_RD0556_01_f_2014_68				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: Control the vegetation on the waterside levee section.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_68\_20150312\_00016.jpg



Unacceptable woody tree growth on the waterside slope and toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	3.69	Rating **	M	Issue No.	58
LM End	4.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.204317 °	38.199502 °
				-121.541259 °	-121.545736 °
DWR ID	DWR_RD0556_01_f_2012_58				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	4.03	Rating **	M	Issue No.	71
LM End	5.47	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.200990 °	38.186502 °
				-121.544037 °	-121.562375 °
DWR ID	DWR_RD0556_01_f_2014_71				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

No Photos

LM Start	4.05	Rating **	U	Issue No.	69
LM End	4.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.995700 °	38.995700 °
				-120.346300 °	-120.346300 °
DWR ID	DWR_RD0556_01_s_2015_69				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comments: There is a rodent hole in crown roadway more than 3-foot deep. The RD need to correct this issue.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_69\_20150430\_00035.jpg



This rodent hole is in the levee crown roadway and goes down some 3-4 foot deep. Repairs are needed.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	4.07	Rating **	M	Issue No.	66
LM End	5.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.200659 °	38.186542 °
				-121.544711 °	-121.562411 °
DWR ID	DWR_RD0556_01_s _ 2013_66				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the wild berries from the slope and toe of the levee section along with the tall weeds.					

No Photos

LM Start	4.07	Rating **	U	Issue No.	67
LM End	5.48	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.200658 °	38.186464 °
				-121.544711 °	-121.562550 °
DWR ID	DWR_RD0556_01_s _ 2013_67				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove the wild weed growth and arundo from the waterside levee section.					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_67\_20150312\_00015.jpg



Unacceptable tall weeds along with arundo present on the waterside slope.

LM Start	4.41	Rating **	M	Issue No.	101
LM End	5.48	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.196325 °	38.186487 °
				-121.547765 °	-121.562548 °
DWR ID	DWR_RD0556_01_s _ 2015_101				
Action/Comments					
Keep the crown roadway free of vegetation.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--



**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015**

**Reclamation District No. 0556 Upper Andrus**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Georgiana Slough	Right	5.48	04/29/2015 04/29/2015	Herman Phillips

LM Start	5.12	Rating **	M	Issue No.	16
LM End	5.29	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.189775 °	38.187967 °
				-121.557729 °	-121.559572 °
DWR ID	DWR_RD0556_01_f_2014_16				
Action/Comments					
Inspector Comments: 1997 - Toe damaged rock. 1999 - One pocket filled with gravel. 2000 - Eroding beach with some biotech rolls and stakes; some gravel on slope. 2001 - Staked, low fascine walls at bankline. 2005 - Stone revetment in between pockets. 2006 - New rock on upper slope behind brush boxes at the upstream end, Stone is sliding off the hard toe. 2013: No observed changes. [2013 Site ID: GEO_7-0_R]					

Photo 1 of 1 : SP\_2015\_RD0556\_18\_16\_20150312\_00004.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	5.72	04/29/2015 04/29/2015	Herman Phillips

LM Start	0.00	Rating **	U	Issue No.	82
LM End	0.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.200550 °	38.200550 °
				-121.544190 °	-121.544190 °
DWR ID	DWR_RD0556_02_s_2013_82				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Both slopes downstream covered with wild growth.					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_82\_20150312\_00016.jpg



Looking downstream waterside slope overgrown.

LM Start	0.08	Rating **	M	Issue No.	287
LM End	2.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.239034 °	38.239923 °
				-121.519684 °	-121.553800 °
DWR ID	DWR_RD0556_02_f_2013_287				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	0.08	Rating **	M	Issue No.	65
LM End	0.14	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.239077 °	38.238935 °
				-121.519714 °	-121.520869 °
DWR ID	DWR_RD0556_02_s_2013_65				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	5.72	04/29/2015 04/29/2015	Herman Phillips

LM Start	0.12	Rating **	U	Issue No.	32
LM End	2.87	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.238939 °	38.229108 °
				-121.520360 °	-121.555298 °
DWR ID	DWR_RD0556_02_f_2014_32				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: The trees should be trimmed up to allow the ground to be seen.					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_32\_20150312\_00011.jpg



Woody tree growth on the waterside levee section.

LM Start	0.31	Rating **	M	Issue No.	28
LM End	0.60	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.238784 °	38.237862 °
				-121.523932 °	-121.529188 °
DWR ID	DWR_RD0556_02_f_2014_28				
Action/Comments					
Inspector Comments: 2002 - Two rocked sections (150 ft long) at the downstream end. 2005 - Lots of old brush boxes, some with established vegetation in the area behind the boxes. 2006 - Some small spots fixed with stone. 2009 - Minimal new erosion, rock in the middle of the reach may be new. 2011 - Minor new erosion at the toe. 2013: Minor new erosion. [2013 Site ID: SAC_26-0_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_28\_20150312\_00010.jpg



USACE 2013 Photo #1

LM Start	1.03	Rating **	M	Issue No.	27
LM End	1.15	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.238772 °	38.239265 °
				-121.536788 °	-121.538845 °
DWR ID	DWR_RD0556_02_f_2014_27				
Action/Comments					
Inspector Comments: 1997 - Rock is in poor condition and has failed in many places.  Scallops in berm with remnants of old rock in the toe area.  2005 - Brush boxes present. 2013: Site extended upstream approximately 300 ft to include new erosion pockets. [2013 Site ID: SAC_25-2_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_27\_20150312\_00009.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	5.72	04/29/2015 04/29/2015	Herman Phillips

LM Start	1.08	Rating **	M	Issue No.	76
LM End	5.72	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.238752 °	38.191803 °
				-121.537687 °	-121.567603 °
DWR ID	DWR_RD0556_02_s_2015_76				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	1.45	Rating **	M	Issue No.	26
LM End	1.59	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.240401 °	38.240772 °
				-121.544106 °	-121.546791 °
DWR ID	DWR_RD0556_02_f_2014_26				
Action/Comments					
Inspector Comments: 1997 - Slow erosion of the berm at the waterline; bench below water. 2005 - Brush boxes present. 2010 - Minor new erosion. 2013: There is little to no berm remaining at downstream end of this site. [2013 Site ID: SAC_24-8_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_26\_20150312\_00008.jpg



USACE 2013 Photo #1

LM Start	1.54	Rating **	M	Issue No.	79
LM End	1.94	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.240452 °	38.240508 °
				-121.545945 °	-121.553017 °
DWR ID	DWR_RD0556_02_s_2015_79				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	5.72	04/29/2015 04/29/2015	Herman Phillips

LM Start	2.07	Rating **	M	Issue No.	55
LM End	2.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.239353 °	38.229938 °
				-121.554998 °	-121.555556 °
DWR ID	DWR_RD0556_02_f_2012_55				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	2.93	Rating **	M	Issue No.	25
LM End	3.04	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.228202 °	38.226601 °
				-121.555502 °	-121.555605 °
DWR ID	DWR_RD0556_02_f_2014_25				
Action/Comments					
Inspector Comments: 1997 - Few scallops in berm, some getting close to levee toe. 2005 - Brush boxes present. 2012 - More erosion of the toe since last year. 2013: No observed changes. [2013 Site ID: SAC_23-3_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_25\_20150312\_00007.jpg



USACE 2013 Photo #1

LM Start	3.16	Rating **	M	Issue No.	23
LM End	3.28	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.224850 °	38.223233 °
				-121.555641 °	-121.555687 °
DWR ID	DWR_RD0556_02_f_2014_23				
Action/Comments					
Inspector Comments: 2000 - Recently fallen cottonwood at the downstream end. 2005 - Empty brush boxes. 2011 - A few trees have fallen since last year. 2012 - Potential new tree popout since last year. 2013: New erosion at downstream end of site and a recent tree pop-out observed. [2013 Site ID: SAC_23-2_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_23\_20150312\_00005.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	5.72	04/29/2015 04/29/2015	Herman Phillips

LM Start	3.24	Rating **	M	Issue No.	18
LM End	3.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.223689 °	38.223419 °
				-121.555370 °	-121.555404 °
DWR ID	DWR_RD0556_02_s_2012_18				
Action/Comments					
Trim and thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	3.58	Rating **	M	Issue No.	22
LM End	3.64	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.218951 °	38.218104 °
				-121.556689 °	-121.556819 °
DWR ID	DWR_RD0556_02_f_2014_22				
Action/Comments					
Inspector Comments: 1997 - Scallops into berm and very close to levee toe. 2005 - Brush boxes present. 2011 - New toe scour and freshly fallen tree. 2012 - New tree popout has taken significant portion of soil out of the levee. 2013: No observed changes. [2013 Site ID: SAC_22-7_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_22\_20150312\_00004.jpg



USACE 2013 Photo #1

LM Start	3.64	Rating **	M	Issue No.	58
LM End	3.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.217984 °	38.217491 °
				-121.556537 °	-121.556630 °
DWR ID	DWR_RD0556_02_f_2012_58				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	5.72	04/29/2015 04/29/2015	Herman Phillips

LM Start	3.83	Rating **	M	Issue No.	16
LM End	4.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			38.215319 °	38.210907 °
				-121.556842 °	-121.556738 °
DWR ID	DWR_RD0556_02_s_2012_16				
Action/Comments					
Thin trees to allow visibility of the ground and room to flood fight.					

No Photos

LM Start	3.95	Rating **	M	Issue No.	21
LM End	4.12	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.213581 °	38.211112 °
				-121.557197 °	-121.557042 °
DWR ID	DWR_RD0556_02_f_2014_21				
Action/Comments					
Inspector Comments: 2002 - Spot rock along berm, but not in the erosion pockets. 2005 - Some new minor stone revetment at the upstream end. Brush boxes present. 2006 - Currently installing new brush in downstream brush boxes. 2007 - Rock in middle portion for about 150 ft. 2010 - Some attempt at repairs but still has pockets of erosion. 2012 - More erosion along the toe. 2013: No observed changes. [2013 Site ID: SAC_22-5_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_21\_20150312\_00003.jpg



USACE 2013 Photo #1

LM Start	4.07	Rating **	U	Issue No.	84
LM End	4.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.211867 °	38.207110 °
				-121.556778 °	-121.556832 °
DWR ID	DWR_RD0556_02_s_2015_84				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2015

### Reclamation District No. 0556 Upper Andrus

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	5.72	04/29/2015 04/29/2015	Herman Phillips

LM Start	4.44	Rating **	M	Issue No.	19
LM End	4.49	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.206379 °	38.205733 °
				-121.557089 °	-121.556999 °
DWR ID	DWR_RD0556_02_f_2014_19				
Action/Comments					
Inspector Comments: 2013: Erosion pockets encroaching on levee foundation. [2013 Site ID: SAC_21-9_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_19\_20150312\_00002.jpg



USACE 2013 Photo #1

LM Start	4.81	Rating **	M	Issue No.	85
LM End	5.72	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.201123 °	38.191803 °
				-121.557147 °	-121.567603 °
DWR ID	DWR_RD0556_02_s_2015_85				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					

No Photos

LM Start	4.85	Rating **	M	Issue No.	3
LM End	4.88	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	USACE Erosion Survey			38.200646 °	38.200225 °
				-121.557606 °	-121.557749 °
DWR ID	DWR_RD0556_02_f_2014_3				
Action/Comments					
Inspector Comments: 1999 - Downstream 140 ft repaired with rock. 2010 - Lots of woody debris, but no changes to site. 2013: No observed changes. [2013 Site ID: SAC_21-5_L]					

Photo 1 of 1 : SP\_2015\_RD0556\_19\_3\_20150312\_00001.jpg



USACE 2013 Photo #1

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--